BULLETIN NO 042021




New Transmission Actuator & Solenoid Dynamometer

Proper communication with the TECU (transmission electronic control unit) used in Mack and Volvo transmissions is critical to ensure proper OE performance. However, these transmissions can be very difficult to accurately trouble shoot.

At ULT we have addressed this potential problem by developing our own in-house proprietary dynamometer testing system that can accurately test the Actuator and Solenoid Valve independently.

Now every actuator and solenoid unit supplied, (new or reman) is tested on this all-new dyno system. The dynamometer interfaces a TECU (transmission electronic control unit) with the OEM application software to test and ensure the actuator and solenoid valve are performing to original equipment specifications.



Current OE Actuator Numbers We Can Test Include:

22429963, 6482 000 155, 23417523, 21580956, 21580977, 22809232, 22440568, 21465235, 21320923, 23417527

See it in Action!



Current OE Solenoid Valve Numbers We Can Test Include:

22327069, 21935705, 21712495, 21462376, 21301883, 21008347, 20483911

Please contact us if you are interested in a machine of your own at 905.612.1256 or www.ultpowertrain.com

Edmonton Alberta 833.442.0442 Mount Pearl Newfoundland 844.442.0442 Moncton New Brunswick 844.442.0442 Quebec City Quebec 844.44<u>2.0442 6</u>

Ottawa Ontario 613.749.4858 Mississauga Ontario 833.442.0442 Winnipeg Manitoba 833.442.0442

WE ARE YOUR ONE-STOP DRIVELINE SOURCE SOLUTION!

ULTPOWERTRAIN.COM